

Simple, non-warranty inspection & quotation process for pop-up aluminium gazebos.

Frames, canopies, walls and other materials can be inspected before any repair quote is confirmed.

Frame or Materials Inspection Fee £25 Per unit, payable before inspection	Non-warranty inspection only The inspection fee covers checking the frame or materials and confirming what repair work is required.
--	--

REPAIR QUOTATION PROCESS

Stage	Cost/Status	Repair Cost
Inspection of frame or materials	£25 per unit	Paid upfront before our team inspects the unit. Applies to non-warranty inspections.
Repair quote	Quoted separately	All repair work is quoted after inspection. There are no standard repair prices.
Repair work	Payment before repair	Repair costs are in addition to the inspection fee and must be paid before work is carried out.

TERMS & CONDITIONS

- All prices are in GBP and exclude VAT unless stated otherwise.
- The inspection fee is £25 per unit for a frame, canopy, wall or other gazebo material item.
- The inspection fee must be paid upfront before our team inspects the unit.
- All repair costs will be quoted separately after inspection and are additional to the inspection fee.
- Payment for approved repair work must be made before repairs are carried out.
- Products should be dry, clean and safe to handle before they are sent or brought in for inspection.

To arrange an inspection, email photos of the frame/materials and damage to:
repairs@instantpromotion.co.uk